



QUIPMENT AVAILABILITY

- BSM Gun Rentals/Spare Parts
- Hot or Cold Gun Equipment
- Delivery

EXPERIENCED EQUIPMENT TECHNICIANS

- Over 60 Years of Combined Know-How
- Support On-Site Installations
- Training and/or Demos Available



MERGENCY MOBILIZATION

Conveniently Located
 24/7 Response

ENHANCED UNI-GUN 85 GP TECHNOLOGY

- Lower Rebounds/Dusting
- Gunned Hot or Cold
- Less Clogging In Gooseneck
- Heated Immediately After Installation



9386_BSM_EQ_SHT_0318

SERVICE

URC UNITED REFRACTORIES CO. S DELIVERS

OVER 45 YEARS OF PERFORMANCE DESIGNED SOLUTIONS APPLICATION: MAJOR SECONDARY PRODUCER LOCATION: NORTHEAST, USA

UNI-GUN 85 GP Gunned Plastic

99,000 lbs. / Low Rebounds / No Clogs!



- 20% Rebounds on Upper Walls with Ceramic Anchors (18-inch centers)
- 15% Rebounds on Belly Band without Ceramic Anchors
- Up to 13.5" Thick (feathered)

• 52 Installs Over Last 37 Months

APPROACH

F

Enhanced GP Technology

- Proprietary plasticity
- Lower rebounds
- Less clogs
- Heat after install

Experienced Technicians

- Over 60 years combined know-how - Support on-site installations

• Equipment Availability

- BSM gun rentals/parts
- Hot/Cold Gun Equipment
- Delivery

Emergency Mobilization

- 24/7 Response - Centrally Located

724•941•9300 • URC4U.com • Sales@URC4U.com

SERVICE

10131_UNIGUN85GP_0421

URC UNITED REFRACTORIES CO. * DELIVERS

OVER 40 YEARS OF PERFORMANCE DESIGNED SOLUTIONS
APPLICATION: ALUMINUM LOCATION: MIDWEST, USA

UNI-GUN 85 GP Gunned Plastic

Less Clogging...Less Rebounds...More Production!

BACKGROUND»

A major aluminum producer has the following

• Repair Area: ... Lower / Upper Sidewalls, hot well and

• Last Repair: ... Competitive 80% Al₂O₃ gunned plastic

• Furnace: 155,000 lbs. Charge Well Melter

charge well

parameters...

URC DELIVERED VALUE»

- Product: UNI-GUN 85 GP Gunned Plastic
- Anchoring: ... None...roughed surface and sprayed phos-bonded mortar on existing lining
- **Repair Thickness:**5" veneer to 13.5" thick
- **Dryout:** With an accelerated heat-up, successfully dried out within tight repair schedule

URC» ADVANTAGES



CAPTIONS - LEFT TO RIGHT

- Aluminum melter lower sidewall repair
- Top ring of round top charge melter repair
- UNI-GUN 85 GP rakes easily
 into BSM equipment

9313_UNIGUN85GP_1117

SERVICE

724•941•9300 • URC4U.com • Sales@URC4U.com

UNITED REFRACTORIES CO.

URC GP Gunned Plastic

Optimizer Makes A GREAT Process Better!

URCI4U

Scan to See an Optimizer Case History

Since 2017, URC has successfully supplied millions of pounds of GP Gunned Plastics to over 70 jobs nationwide.

Now, URC introduces The Optimizer...

a proprietary process improvement that reduces costs, increases speed and improves install variables.

Features	Benefits
Bulk Bag Packaging No cardboard totes	Improved productivity and less waste.
• NO RAKING! Direct feed to BSM Gun	Safer install, improved ergonomics and less labor required.
Uniform/Consistent Feed to Gun	• Lower rebounds, less surging and no tape balls!
• Higher Install Rate	• Up to 2 times faster!

The Optimizer Service Package

Available exclusively from URC, together with our:

- BSM Gun Rental
- "Best in class" On-site Support
- Rapid Delivery Response



URC's Line of GP Gunned Plastics

- UNI-GUN 85 GP AL • UNI-GUN 85 GP
- UNI-GUN BLU J GP • UNI-GUN GREEN GP

724•941•9300 • URC4U.com • Sales@URC4U.com

URC GP Gunned Plastic

UNITED REFRACTORIES CO. DELIVERS

UDUMZEP + UNI-GUN 85 GP AL = *Maximum Performance!*

CASE HISTORY

Aluminum Furnace Repair (60,000# UNI-GUN 85 GP AL)

- UNI-GUN 85 GP AL reduces metal penetration and adherence while improving cleanability.
 - * The first "non-wetting" gunned plastic!
- Using The OPTIMIZER, the crew achieved a 10,000#/hr. rate
 * Typical practice is approximately 6,000#/hr.
- Super Sacks were used with
 The OPTIMIZER, instead of boxes, using a
 3-man crew with no raking.
 *Typical is 4-man crew
- With improved consistency of the OPTIMIZED UNI-GUN 85 GP AL, the flow, quality and consistency was vastly improved, with NO TAPE BALLS used. * Typical usage is 50-100 tape balls!



- 66% Faster
- Reduced Labor
- Increased Safety
- Less Waste
- Higher Quality
- Increased
 Productivity



Scan to See an Optimizer Deliver Sheet

URCI4U